


RCR201/5





1


RCR201/6



RCR201/56
RCR201/56A




RCR201/5
RCR201/6




2

RCR201/5




3

RCR201/6




RCR201/5




4




RCR201/6



RCR201/5



5




38

	P P bar	0,5 MIN	MAX 10	5 1	
	T T °C	80	MAX	65 45	



IISTR00201/5#--NEU

REV2.12/2019








Not included / Non incluso / Non Inclus / Nie zawarty / No incluido / Nao incluido










1



RIFERIMENTO ALLA PIASTRELLA
REFERENCE TO THE TILE






www.grupponobili.it

PRIMA DI INIZIARE / BEFORE STARTING



PULIZIA / CLEANING



Достоверную информацию уточняйте на santehnica.ru.